

Standard Operating Procedure (SOP)

Welding Machine Operations

Document No.	SOP-WELD-001
Revision No.	1.0
Effective Date	YYYY-MM-DD
Prepared By	[Name]
Approved By	[Name]

1. Purpose

This SOP outlines the standard procedures for safe and efficient operation of welding machines.

2. Scope

Applies to all personnel operating welding machines in [Department/Location].

3. Responsibilities

- Operators must follow the steps outlined in this SOP.
- Supervisors ensure compliance and provide necessary training.

4. Required Materials and Equipment

- Welding machine
- Personal protective equipment (PPE): Helmet, gloves, apron, goggles
- Welding rods/wire
- Earth clamp and cables
- Fire extinguisher

5. Procedure

5.1 Pre-Operation

- Inspect welding machine, cables, and connections for damage.
- Ensure PPE is worn at all times.
- Check ventilation in the work area.
- Remove any flammable materials nearby.
- Set up warning signs/barriers as needed.

5.2 Machine Setup

- 1. Connect earth clamp to workpiece.
- 2. Select correct welding rod/wire and settings.
- 3. Switch on the machine.
- 4. Adjust current/voltage according to material and procedure.

5.3 Welding Operation

- 1. Hold torch securely and use proper technique.
- 2. Monitor weld quality and adjust as needed.
- 3. Stay alert for overheating or unusual noise.

5.4 Post-Operation

- 1. Switch off the machine and disconnect power.
- 2. Allow equipment to cool before handling.
- 3. Clean work area and store machine and tools properly.
- 4. Report any issues to supervisor immediately.

6. Health, Safety, and Environmental Considerations

- Always wear appropriate PPE.
- Ensure fire extinguisher is accessible.
- Ensure adequate ventilation to avoid inhaling fumes.
- Follow emergency procedures in case of an incident.

7. Documentation

- Record details in the welding log after each use.
- Report and document any malfunction or deviation.

8. Revision History

Revision	Date	Description	Prepared By	Approved By
1.0	YYYY-MM-DD	Initial Release	[Name]	[Name]