

Earthquake Property Loss Claim

Claimant Name

Property Address

Date of Earthquake

Policy Number

Contact Number

Email Address

Description of Damages

Itemized Losses

Item	Description	Estimated Value
Roof	Cracked and missing shingles, structural compromise	\$7,500
Walls	Major cracks in living room and bedroom walls	\$4,000
Windows	Broken glass and window frames in kitchen	\$1,200
Total		\$12,700

Additional Information

